



equinor


Completion and Production Challenges in Offshore Heavy Oil – Lessons Learnt from Peregrino

Luiz Fernando Pastre – Completion Engineer



Peregrino Field | Brief History

- Block BM-C-7 in Campos Basin – 85 Km offshore Brazilian coast.
- Discovered in 1994.
- Estimated reserves of 400 million barrels of recoverable oil.
- Heavy oil reservoir (13 deg API).
- Oil viscosity: 390 cP.
- Equinor became field operator in 2008.
- Exploration license for adjacent block BM-C-47 acquired in 2008.
- New block added 273 millions barrels in recoverable reserves.



Legend

- Equinor operator
 - ▨ Equinor partner
 - Other licences
 - ▤ Pre-salt area
 - Producing field
 - Field discovery
 - Equinor office
 - Capital
 - Apodi solar
- 0 100 km

Peregrino Field | Field Development

- Field structure consists of 2 drilling capable platforms and 1 FPSO.
- Oil production started in 2011 using ESPs as artificial lift method.
- Current field production is 60-80k barrels of oil a day.
- Over 200 million barrels of oil already produced.
- Third fixed platform under commission for phase II development.
- Largest field operated by Equinor outside Norwegian continental shelf.




Peregrino Field | Well Design

- **Well Design**

- Long horizontal sections - up to 7,200 ft.
- Extended reach wells – up to 28,600 ft.


- **Lower Completion Design**

- Sand screens deployed in every well.
 - ✓ Detailed torque and drag analysis required.
 - ✓ Landing string selection.
 - ✓ Swivel device.
- Open Hole Gravel Pack design.
- Autonomous Inflow Control Devices installed in the sand screens.
 - ✓ Very light weight proppant.




Upper Completion | Standard Design

- 5-1/2" L80 production tubing.
- 9-5/8" ESP production packer.
- Diverter valve above ESP string.
- 675 series pumps driven by 1100HP tandem motors.
- Two independent chemical injection systems.
- Formation isolation valve installed in the middle or lower completion.
- Shifter assembly installed in the tailpipe below the ESP string.
- Middle completion required depending on casing shoe and ESP setting depth.




Upper Completion | Improvements

- Encapsulated ESP design.
 - ESP installed inside a 7-5/8" capsule.
 - Doesn't require a packer above ESP string.
 - Allows ESP to be set deeper.
 - Reduces mechanical stress applied to ESP components due to tailpipe weight.
 - Eliminates the need of a middle completion.
 - Compromises production in some cases.
- Production tubing grade replaced with P110.
- Introduction of a control line set packer which doesn't require plug installation.
- Reinforced downhole gauge and flange design.




Production Challenges | ESP Performance in Heavy Oil

- Affinity laws don't hold true for high viscous applications.
- Head and rate are de-rated due to fluid viscosity.
- Excessive power consumption due to low system efficiency.
- Performance models available in the literature are validated with a specific stage type.
- Lab tests limited due to bench constraints.





ESP Qualification | Equinor Technical Requirements

- Each ESP pump type shall be tested with synthetic oil for viscous applications.
- A pump with minimum 6 stages shall be used.
- Viscosity range and operational frequencies are defined by the application.
- System integration test performed in the Product Centre for each string type.
- Stack-up test including completion equipment performed for each string type in Brazil.
- Factory acceptance test performed for every ESP component in Brazil.



ESP Production | Emulsion

- ESP shear forces create emulsion.
- Emulsion viscosity increases up to phase inversion point.
- Higher viscosity degrades ESP performance.
- Emulsion breaker is injected to control emulsion formation.
- Emulsion production creates instability in ESP parameters.
- Pressure and temperature cycles create an ageing effect in downhole equipment.



ESP Failure Modes | Packer Penetrator


- Epoxy with cracks leading to phase-phase and/or phase ground failures.
- Fluid contamination inside packer penetrator.
- Signs of overheating noticed during teardown.
- Packer penetrator upgraded to HPHT design.
 - Pressure rating: 10k psi absolute and 5k psi differential.
 - Temperature rating increased to 180 deg C.
 - Insulation materials improved.
- 38 HPHT packer penetrator installed in Peregrino without any failure.



ESP Failure Modes | Asphaltene Precipitation


- Created by chemical instability between dielectric oil and heavy crude.
 - Bag expansion capacity reduced.
 - Check valves plugged.
 - Mechanical shaft seal operation compromised.

- Asphaltene resistant seal design
 - Particle expulsion holes in top chambers.
 - Communication holes in housing.
 - High pressure check valves.
 - Anti-asphaltene additives added to seal section oil.



Peregrino Operation | Way Forward

- Continue failure analysis focus and introduction of new technology.
- Close partnership with Universities and Research Centres to better understand ESP performance in viscous applications.
- Evaluate improvements achieved by the implementation of the performance based contract.
- Deploy ESP discharge temperature reading in 100% of the wells.
- Implement ISO 15551 qualification.
- Achieve consistent 3 years run life in the field.
- Eliminate premature failures.



Completion and Production Challenges in Offshore Heavy Oil – Lessons Learnt from Peregrino

Luiz Fernando Pastre – Senior Completion Engineer

© Equinor ASA

This presentation, including the contents and arrangement of the contents of each individual page or the collection of the pages, is owned by Equinor. Copyright to all material including, but not limited to, written material, photographs, drawings, images, tables and data remains the property of Equinor. All rights reserved. Any other use, reproduction, translation, adaption, arrangement, alteration, distribution or storage of this presentation, in whole or in part, without the prior written permission of Equinor is prohibited. The information contained in this presentation may not be accurate, up to date or applicable to the circumstances of any particular case, despite our efforts. Equinor cannot accept any liability for any inaccuracies or omissions.